

Oil Field Environmental Incident Summary

Incident: 20150213101735 **Date/Time of Notice:** 02/13/2015 10:17

Responsible Party: Triangle USA Petroleum Corp

Well Operator: TRIANGLE USA PETROLEUM CORPORATION

Well Name: Paulson 150-101-23-14-1H

Field Name: RAWSON

Well File #: 28917

Date Incident: 2/11/2015 **Time Incident:** 10:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 101

Sec: 23

Qtr: SE SW

Location Description: Mostly on well/facility site however some crude spray did mist onto snow covered neighboring land.

Submitted By: Brittany Vannoy

Received By:

Contact Person: Brittany Vannoy
1200 17th St Suite 2600
Denver, CO 80202

General Land Use: Other - Described Above

Affected Medium: Soil and Water

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units
Oil	0.5	Barrels

Recovered	Units
-----------	-------

Followup	Units
----------	-------

Brine

Other

Description of Other Released Contaminant:

Crude oil

Inspected:

Written Report Received: 3/7/2016

Clean Up Concluded: 2/11/2015

Risk Evaluation:

None.

Areal Extent:

20 x 300 most of it on the facility location, 15' mist onto surrounding land.

Potential Environmental Impacts:

None.

Action Taken or Planned:

The well was immediately shut it, preventing additional release of fluid. The spill will be remediated.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 2/13/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 2/19/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

10:21 The weather is cloudy, 20 °F with wind from the southeast at 10 mph. Called contact who submitted the spill report, and she indicated that the west well was the one that sprayed. The spray went south on to a road and field. I could not see anything on the road and in the field at this time. The area has a small amount of fresh snow, and the ground is frozen. It was indicated that the landowners were contacted and were agreeable to leaving the sprayed area alone. Further followup needed. 47 47.477, - 103 34.243

Date: 2/25/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

General information.

Date: 3/3/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received information on the site regarding how the spill occurred and was handled.

Date: 4/1/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 11:00 a.m. The weather is clear, 54°F, with the wind from the west at 30 mph. The area is clear of snow, and I did not see any oil staining in the field or on the pad bank. No further followup needed.